

















































Class 1 Illustrations



Material configuration	Location of needle penetration or passage	Numerical designation
1.01 		1.01.01 1.01.02 1.01.03 1.01.04 1.01.05
1.02 		1.02.01 1.02.02
1.03 		1.03.01
1.04 		1.04.01 1.04.02
1.05 		1.05.01
1.06 		1.06.01 1.06.02 1.06.03 1.06.04

<p>1.07</p> 		<p>1.07.01</p>
<p>1.08</p> 		<p>1.08.01</p>
<p>1.09</p> 		<p>1.09.01</p> <p>1.09.02</p> <p>1.09.03</p> <p>1.09.04</p> <p>1.09.05</p>
<p>1.10</p> 		<p>1.10.01</p> <p>1.10.02</p> <p>1.10.03</p> <p>1.10.04</p>
<p>1.11</p> 		<p>1.11.01</p>

<p>1.12</p> 		<p>1.12.01</p>
<p>1.13</p> 		<p>1.13.01</p>
<p>1.14</p> 		<p>1.14.01</p>
<p>1.15</p> 		<p>1.15.01</p> <p>1.15.02</p> <p>1.15.03</p>
<p>1.16</p> 		<p>1.16.01</p> <p>1.16.02</p>
<p>1.17</p> 		<p>1.17.01</p>


<p>1.18</p> 		<p>1.18.01</p>
<p>1.19</p> 		<p>1.19.01</p>
<p>1.20</p> 		<p>1.20.01</p>
<p>1.21</p> 		<p>1.21.01</p> <p>1.21.02</p>
<p>1.22</p> 		<p>1.22.01</p>
<p>1.23</p> 		<p>1.23.01</p> <p>1.23.02</p> <p>1.23.03</p>
<p>1.24</p> 		<p>1.24.01</p> <p>1.24.02</p>

1.25



1.25.01

1.26



1.26.01